



APPENDIX - VIII

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.

No. G.O. No. 12

Date : 30/8/22

It is certified that an inspection team headed by Er. Apu Purkayastha
J.E., DWS Sub-Div. Dharmnagar (Name of Officers
with designation) from _____ (Name of
Department/Office) inspected the NORTH POINT SCHOOL
Chandrapur, Haritala, Dharmnagar (N) Tripura (Name & Address of
the School) on 22/08/2022 and found that the NORTH POINT SCHOOL
Chandrapur, Haritala, Dharmnagar (N) Tripura (Name of school) has safe
drinking water facilities for the students and members of staff of the institution and is maintaining
the hygienic sanitation condition in the school building & the campus as per the norms
prescribed by the Central/State/U.T Govt.

The above valid for a period of 6 (Six) months

Signature with Seal : _____

Assistant Engineer

Name

: D.W.S. Sub-Division
Dharmnagar, North Tripura

Designation

: _____

To

The Principal
North Point School
Chandrapur, Haritala, Dharmnagar

(Name & Address of the Institution)